

PCI, TR-31 Keyblock Info

The Easy

üB3 and B5 Keypads CAN support TR-31

üB3's started shipping in April of 2014

üWill require software update when the time is right





PCI, TR-31 Keyblock Info

The Good

üB1 and B2 Keypads will NOT support TR-31

üKeypad & Bracket must be replaced

üSoftware update may be required to support B5 (.37)





PCI, TR-31 Keyblock Info

The: Its Going To Be Okay

üC4000 with ACU1 Board will not support TR-31

ü2006-2008 – So they are minimum 14 years old

üMust replace motherboard

üMust replace keypad & mounting hardware





PCI, TR-31 Key Block Timeline - Estimated

Approximate date of manufacturing
Keypad Type
Action required for ATM to be compliant

Pre 2006

2006-2008

2008 - 2014

2014 - Current

B1 EPP Embedded

B1 EPP C4000

B1 and B2 EPP

B3 and B5 EPP

Replace unit

- Replace keypad

Change out board

- Software update

- Replace keypad

- Software update

Software update



Questions?

